

ARMOR SERIES OF HDD ENCLOSURE



Introduction

Accessories



Power adapter



Power cord




USB cable



SATA cable



Manual



Driver CD



Screwdriver




SATA Power cable

Minimum System Requirements


- Intel® Pentium® III 450MHz or compatible processor
- Microsoft® Windows® XP, Windows 2000, Windows Me (Millennium) or Windows 98 SE (Second Edition) 128 MB RAM
- Available USB port (version 1.1 or later)

Installation


IDE HDD Installation




1. Remove the four marked screws on the back of the enclosure with the screwdriver.




2. Take out the built-in shield case.



3. Open the shield plate.



4. Install your IDE hard disk drive and secure it with the screws.



5. Cover the shield plate and secure the shield case to the aluminum enclosure with screws. Installation completed.

Installing Product Drivers

In Windows XP, Windows 2000 and Windows Me

Upon connecting your Armor Portable HardDisk to a computer for the first time, Windows automatically installs the required drivers. Your Armor Portable HardDisk is detected as a Mass Storage Device and no additional drivers are required.

In Windows 98 SE

1. Upon connecting your Armor Portable HardDisk to a computer for the first time, the **Add New Hardware** dialog box appears.
2. Click the **Next** button.
3. Select the **Search for the best driver for your device** option, and then click the **Next** button.
4. Select the **CD-ROM drive** check box.
5. Insert the Driver Installation CD into your CD/DVD-ROM Drive, and then click the **Next** button. Windows searches for the necessary files and lists them in the next dialog box.
6. Click the **Next** button. Windows copies the necessary files to your computer.
7. Click the **Finish** button to complete the installation.

Disconnecting Your Armor Portable Hard Disk



To prevent data loss, ensure that:

- You have disconnected your Armor Portable Hard Disk properly in Windows before unplugging it from the USB port on your computer (refer to the steps for your respective operating system)
- You do not unplug your Armor Portable Hard Disk from the USB port on your computer when transferring files to or from the device, or when files or applications stored on your Armor Portable Hard Disk are in use

In Windows XP, Windows 2000 and Windows Me

1. Click the **Safely Remove Hardware** icon on the Taskbar and Click **Safely remove USB Mass Storage Device**.




2. Unplug your Armor Portable HardDisk when you are prompted To do so.



This prompt appears on the Taskbar in Windows XP. On other operating systems, a message box appears on the desktop instead.

In Windows 98 SE

1. Wait at least 10 seconds after all file transfers are completed.
2. In Windows Explorer, right-click the **Removable Disk** icon. And click **Eject**.
3. Unplug your player after 10 seconds.



ARMOR

WARNING:

When using this product, please avoid vibrating heavily and colliding with other products, prevent the damage of hardware or data losing.